VACUUM PUMP

PCE-VPP 16



- **Pressure range: -0.88...16 bar**
- **Accuracy:**
- **Medium: air pressure**

This reference measuring device can generate negative pressure/vacuum and pressures up to 16 to 25 bar (depending on the model). An additional pressure gauge (optional) is required for the reference measurement of the set pressure. The fine adjustment on the valve allows any calibration pressure to be set quickly and precisely. This reference measuring device is ideal for testing measuring instruments, e.g., pressure gauges and pressure transmitters. The reference device for precise actual pressure measurement screws directly onto the hand pump.

Specification

Pressure	
Measuring range	-0,88 ... +16 bar
Resolution	0,01 bar

General technical data	
Connections	1/4 NPT (male thread), M14 x 1.5 (internal thread)
Measuring medium	Air
Operating conditions	0 ... 40 °C , 5 ... 95 %RH
Storage conditions	0 ... 40 °C , 5 ... 95 %RH
Dimensions (L x W x H x ø)	230 x 107 x 65 x 34,2 mm
Other dimensions	Cable length: approx. 30 cm
Weight	790 g

PCE Americas Inc. dba PCE Instruments
1201 Jupiter Park Drive, Suite 8
Jupiter, FL 33458
USA

Phone: +1-561-320-9162
info@pce-americas.com