
DUROMETER

PCE-DX-AS



- **With drag needle**
- **Measures in different hardness units**
- **A 36º dial**
- **Highly accurate**
- **Meets with all standards**
- **Supplied with a small carrying case**

This is a hardness tester is used for measuring surface hardness (shore A) of hard rubbers and soft plastics. The shore hardness tester is composed of a single component with a measuring head and a 36º dial. To improve the readability of peak value, the device comes with a drag needle, that ensures the maximum reading can be captured. Once it has been measured, it can be reset to zero. With the model of hardness tester, you will always obtain the most accurate value of maximum pressure and also be able to accurately reproduce this value.

Specification

Hardness	
Measuring range	10 ... 90 Shore A
Resolution	1 Shore A
Accuracy	±2 Shore A

General technical data	
Contact force	0 ... 12.5 N
Penetrator	35°
Dimensions	Watch diameter: 57 mm / 2.24 in
Operating conditions	0 ... 40 °C , 0 ... 80 (non-condensing)%RH
Storage conditions	-10 ... 60 °C , 0 ... 80 (non-condensing)%RH
Dimensions (L x W x H)	115 x 62 x 26 mm
Weight	160 g

PCE Americas Inc. dba PCE Instruments
1201 Jupiter Park Drive, Suite 8
Jupiter, FL 33458
USA

Phone: +1-561-320-9162
info@pce-americas.com